



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Outgoing
C0070033
#4095
K

June 5, 2012

James A. Hewlett, Resident Agent
Intermountain Power Agency
10653 South River Front Parkway, Suite 120
South Jordan, Utah 84095

Subject: Midterm Review Completion Response, Task ID #4095, Intermountain Power Agency, Wildcat Loadout, Permit C/007/0033

Dear Mr. Hewlett:

On May 9th, 2012, the Division of Oil, Gas and Mining (the Division) received the Midterm Review Completion response from Intermountain Power Agency (the Permittee) for the Wildcat Loadout facility.

The Division has identified deficiencies that must be addressed prior to issuance of final approval. The deficiencies have been included with this letter (See Attached). The name of the author for each of the respective deficiencies has been provided.

Your response to these deficiencies will need to be submitted as an amendment to your MRP and will be processed as a separate task. Please submit the required amendment with the accompanying C1 and C2 forms by no later than July 9, 2012.

If you have any questions, please don't hesitate to call me at 801-538-5325 or Peter Hess at 435-613-3731.

Sincerely,

Daron R. Haddock
Coal Program Manager

DRH/SKC/ss
cc: Price Field Office
O:\007033.WCL\WG4095\WG4095DefLtr.doc



Deficiency List
Task No. #4095
Midterm Review Completion Response

The members of the review team include the following individuals:

Steve Christensen (SC)
Joe Helfrich (JH)

R645-301-742: The Permittee must revise Appendix R to reflect the sediment control measures to be implemented as agreed upon at the December 13th, 2012 meeting with the Division of Oil, Gas and Mining. The previous technical analysis directed the Permittee to revise page 2 of Appendix P and page 1 of Appendix R to address outstanding sediment control measures. Upon review of the amendment, it appears that Appendix R was not revised. (SC)

R645-301-512.100, -512.200 and -731.720: The Permittee must provide a professional engineered stamp on Plate 2A, *Wildcat Loadout Proposed Drainage Map Response to DO-04* and Plate 3B, *Wildcat Loadout Sediment Pond "B"*. The Division acknowledges that the Addendum to Appendix R, *Sediment Pond B* was stamped on the cover page by J. Thomas Paluso; however, R645-301-512.100 and -512.200 require that the impoundment cross-sections and maps must be stamped by a professional engineer. R645-301-731.720 requires professional engineer certification for a map that depicts the locations of each water diversion, collection, conveyance, treatment, storage and discharge facility to be used at the site (i.e. Map 2A). (SC)

R645-301-121.200, -742: The Permittee must revise Plate 2A, *Wildcat Loadout Proposed Drainage Map Response to DO-04*. The submitted Plate 2A is exceedingly difficult to read/interpret due to its size and the use of one color. The currently approved Plate 2A is of sufficient size and utilizes different colors to differentiate between the various components of the drainage system at the site. Please re-submit Plate 2A in a similar format/sizing. (SC)

R645-300-143, the Permittee needs to provide the Division a description of the current status of action items 2, 3, 5, 6 and 7 noted in appendix P of the MRP, Division Order DO-04. If these items have not been completed the Permittee needs to meet with the Division staff and submit a timeline for implementation of each item. (JH)